TECH INTERNATIONAL

200 E. Coshocton St. P.O. Box 486 Johnstown, OH 43031 Phone 740/967-9015 Fax 740/967-3583 www.techtirerepairs.com

May 13, 2008

MEMO TO:

All ITD's and Distributors

FROM:

Todd Kirkpatrick

RE:

Baolong Snap-In Valves

It has come to our attention that a few customers have experienced problems with the Baolong TRI413 or TRI418 snap-in valves. Tech International is looking into this matter and we are testing valves that are in question. Within the next two weeks, you will be receiving a document explaining correct procedures to handle any valve complaints.

We have inspected all current inventories of TRI413 and TRI418 valves and Tech can verify, based upon the attached letter, that all valve products in stock meet the SAEJ1025/1206 standards. When you receive the document explaining procedures to handle valve complaints, please review and provide us with any comments.

We appreciate your cooperation.

Regards,

Jan J. Hills

05.13.08Baolong Snap-In Valves.doc